

### Magic-Pak® V-Series™ Drier Changes

In 2015 changes to the Magic-Pak® V-Series™ were implemented to meet new efficiency and application requirements. This included moving some Magic-Pak® V-Series™ to rotary compressors.

We received early reports of stress cracks forming near the liquid line drier. To eliminate this potential issue, the location of the filter drier has been moved. Beginning with serial numbers 1617F, driers will be located on the suction side of the compressor. This will provide compressor and system protection and eliminate the potential leaks at the liquid drier.

Also, service ports are being added to the suction drier to enhance serviceability.

If you have any questions, please contact Allied Technical Service at 800-515-3501.

FOR DEALER DISTRIBUTION